thereafter will require that you click the Update Model button, unless you wish the software to renumber or recalculate the solution set. In that case, you will click the Identify Sensors button.

Figure 8-1 shows a flowchart of the marking process, and Figure 8-2 shows a flowchart of the **editing** process. The sections that follow these flowcharts provide additional information about these procedures.




Figure 8-1. Sensor marking




Figure 8-2. Editing points