




CREINTORS AUTOMATION SOLUTIONS PVT.LTD.



PRESENTS

HONOR'S PROGRAM IN PLC PROGRAMMING







Syllabus of Course



1. Basics of PLC



2. PLC Programming

3. SCADA Programming



PLC Programme










Motor Control Circuit - DOL



DOL - means Direct On Line Starter



SO = 'OFF' Push button
S1 = 'ON' Push button
K1 = Main contactor
F1 = Main circuit fuse
F2 = Overload relay
F3 = Control circuit fuse








Sensors Linking to Network





IO-Link is a short distance, bi-directional, digital, point-to-point, wired (or wireless), industrial communications networking standard (IEC 61131-9) used for connecting digital sensors and actuators to either a type of industrial fieldbus or a type of industrial Ethernet.

