


#### PIS program modify add F1:CSV to export production data to CSV file.




**Purpose:** Additional function F1:CSV to export data from production data screen.

Remarks: CSV file format see attached file CSV format.xls

Due date: Before 26 Sep. 2011



### PIS program modify separate mass production data.



Purpose: Modify and add function key F1:MASS(LA) and F7:MASS(UA) to separate production data of LA line and UA line.

Remarks: 1.LA: seq.no. = Lxxxxxx

2.UA: seq.no. = Yxxxxxx



# PIS program modify add pop up for confirmation after edit flow setting.

yrik Sike-950 valid valvas eta ekstana eta	segerilar eta Masayet Andrewsee	esternos de despues. Planetros de	- <b>1286</b> ‡	64 Oct.	Fine size of fiverel schedule	Distributed of Soliton pro-plan landers	blanch ar still Fall ha Snech		Advance	Howers	UNIT	BLOCK	The size of fixed schedule	Member of let to create index	
tre .			5	•		f	The entire to verify	CPI	O		5	1			The settings
	5	9	5	1				MA 11	Dâ,	rλ	5	יתו' דא	DIT	700	[ [ [ [
			5	1	15	3	1	M/G	UA.		UAL 5		171 I 15	3	1
ŕ	S.	0	5	1											
,	10 20	0	5	3				S/M SUB ALC	9	4	5				
			Carrier 1	Parts Flo	HW			5.M SUB 8	•	0	5	3			
fronte		510		655		MAL J	PEOLIST BIN	CTION (SAME	AC DEI		INICTI				
fronte	201 ··· 201 ··	510	CONI	FIRM	CHAN	Annual Control of the		ICTION (SAME	AS DEL	LETE FL	JNCTIC				
fic-sece	201 ··· 201 ··	510	CONI	655	CHAN	NGE R		ICTION (SAME	AS DEL	ETEF	JNCTIC	DN)			
fire-saice	201 ··· 201 ··	510	CONI	FIRM	CHAN Do you	NGE R	REQUEST FUN	ICTION (SAME	AS DEL	ETE FL	JNCTIC	ON)			
Starbite :	201 ··· 201 ··	510	CONI	FIRM onfirmb	CHAN CHAN Do you	NGE R	REQUEST FUN	ICTION (SAME	AS DEL	ETE FU	JNCTIC	ON)		CL	OSE
	201 ··· 201 ··	510	CONI	FIRM onfirmb	CHAN Do you	NGE R	REQUEST FUN	ICTION (SAME	AS DEL	LETE FU	JNCTIC	ON)			OSE MP CI


**Purpose:** Additional confirmation pop up after edit flow setting.

**Remarks:** 1. This function can be change the password for confirmation.

2.Can add user name maximum 5 users.



# PIS program modify condition for select skip production data.




**Purpose:** 1.Delete Model Code / Block Model select function.

2.Modify select codition of Model Code / Block Model + Lot No. and Model Code / Block Model + Lot No. + Unit can select production data by multi selection.

**Remarks:** 



## PIS program modify sorting skip production data on skipdata screen by ascending.




**Purpose:** Modify sorting seq.no. on skipdata sreen by ascending (A-->Z and 1,2,3,...,n.)

**Remarks:** 



### PIS program modify dummy data function.




Purpose: 1.On production data screen modify add dummy data by automatic (can input number of dummy data).

2.On production data screen modify can delete dummy data by multi selection.

**Remarks:** 



## LMS program modify calculate taget by use working ratio from PPC plan (exel file).



**Purpose:** 1.Modify taget formular by use working ratio from PPC plan (excel file from PPC.).

Remarks: