

## Linear Systems: Single Input Single Output View Assignment

1. Write down the differential equation representing relationship between the loop current  $y\left(t\right)$  and the input voltage  $v\left(t\right)$ . Assume a initial loop current of  $y\left(0^{-}\right)=y_{0}$ .



- (a) Find the response of the system for the input  $v\left(\bullet\right), \forall t\geq0$  shown in the figure.
- (b) Show that for a suitable choice  $\epsilon$ ,  $y\left(t\right)=0, \ \forall t>\epsilon.$
- (c) Assuming  $y(0^-)=0$ , what happens to y(t) when,  $\epsilon \to 0$  and  $v_0 \to \frac{1}{\epsilon}$ ? Derive the mathematical expression applying this limit. Compare this solution to the input  $v(t)=\delta(t)$ .
- (d) What will happen when  $\epsilon \to 0$  and  $v_0$  is constant?
- 2. Derive the differential equation governing the following two mechanical systems. The input to both these systems is the force f(t), and the position x(t) is the output; assume the initial conditions to  $x(0^-)$ ,  $\dot{x}(0^-)$ .




Find the expression for the step response of these two systems.

3. Consider a continuous-time LTI system with impulse response,  $h\left(t\right)=e^{-2t}1\left(t\right)$ . What is the output of this system to the following inputs using the convolution integral? (a)  $e^{-2t}1\left(t\right)$ ; (b)  $e^{-2t}$ ; (c)  $e^{-1t}$ ; (d)  $e^{-4t}$ ; and (e)  $\cos\left(\omega t\right)$ .

Now, obtain the expression for the output of the system for the above inputs using the system's transfer function  $H\left(s\right)$ .

4. Find the impulse response and transfer functions of the following composition of subsystems with individual impulse response  $h_i(t)$ .



5. Consider the second order system,  $\ddot{y}(t) + 2\zeta\omega_n\dot{y}(t) + \omega_n^2y(t) = u(t)$ . Find the impulse response of this system. Plot the impulse response of the system for  $\omega_n = 1$  and the following values of the parameter  $\zeta$ . (a)  $\zeta = \sqrt{2}$ ; (b)  $\zeta = 1$ ; (c)  $\zeta = 0.5$ ; (d)  $\zeta = 0$ ; (e)  $\zeta = -0.5$ ; and (f)  $\zeta = -1.0$ ; For each of these parameter values show the location of the poles of the corresponding transfer function.