


## Exp No: 3 STEPPER MOTOR USING AT89C51 USING PROTEUS

### CIRCUIT DIAGRAM:



### PROGRAM

```

1  ORG 0000H
2  UP: MOV P2,#0AH
3  ACALL DELAY
4  MOV P2,#06H
5  ACALL DELAY
6  MOV P2,#0CH
7  ACALL DELAY
8  MOV P2,#09H
9  ACALL DELAY
10 SJMP UP
11 DELAY:MOV R4,#18
12 H1:MOV R3,#255
13 H2:DJNZ R3,H2
14 DJNZ R4,H1
15 RET
16 END

```