

Practice Problem 2.11

Sketch Tools & End Conditions (Level 2)

- Units: MMGS
- Difficulty Level: Easy
- Certification: CSWA
- Duration (min): 10
- Design Intent:
 - The part's origin location is indicated in red.
 - The part is symmetric.
 - All sketches are fully-defined.

Suggested Sketch Tools / Features

- Sketch: Lines, Centerlines, Circles, Sketch Mirror, Trim, Convert Entities
- Features: Extrude Boss

Volume: 1387 mm³

