

Practice Problem 2.20

Sketch Tools & End Conditions (Level 2)

- Units: MMGS
- Difficulty Level: Medium
- Certification: CSWA
- Duration (min): 10
- Design Intent:
 - The part's origin location is indicated in red.
 - The part is symmetric.
 - All sketches are fully-defined.

Suggested Sketch Tools / Features

- Sketch: Lines, Circles, Arcs, Polygons
- Features: Extrude Boss

HINT: Bosses are centered on the edges.

Volume: 50984 mm³

