NON-CONFORMANCE REPORT CONSTRUCTION

Project :	*VTP BELLISSIMO*
Location :	*Tower-08*
Discipline :	*RCC*
System/Consequences :	*RCC*

NCR No : *NCR-BELLISSIMO-110*	**Initiator :** *Mr. Hitesh Bhadekar*	**Comapany :** *VTP Realty*

Drawing/Specification /code /procedure Reference No :Approved mockup /Sample

Assignee: *Mr. Sandip Mane*	**Contractor:** *M/s. Karan Builders*	**Date/Time :**	*20-05-2025*

Subcontractor / Purchase Order.No.:

DESCRIPTION : Non-conformance : Non-Conformance ☒ **Observation** ☐ **Major** ☒ **Minor** ☐ **Severe** ☐

1. Concrete chipping not done in proper way.

2. Reinforcement steel exposed after chipping.

3. Tower-08, Flat no. 2, 8SW25, common shear wall for master and common bedroom.

PROPOSED CORRECTIVE ACTION (CLIENT/ASSIGNEE : *) Re-work /Repair ☐ **Scrap** ☐ **Use As is** ☐

PROPOSED PREVENTIVE ACTION (CLIENT/ASSIGNEE:*)

Initiator Name & Signature	*Mr. Hitesh Bhadekar*	**Date:**
Site In-charge Name & Signature :	*Mr. Sandip Mane*	**Date:**
Client Incharge Name & Signature :	*Mr. Anand Jadhav*	**Date:**

Resolution Required By : **Immediate** ☐ **24 Hours** ☐ **Specify** ☐

CORRECTIVE ACTION IS COMPLETED,ACCEPTED & NCR CLOSED OUT

Contractor Tower Incharge	Contractor Quality Incharge	Client Tower Incharge	Client Quality incharge
Sign: Name: Date:			

* Delete as appropriate

EVIDANCE SNAP