



SPC IN PRODUCTION

5 tips for effective use of control charts



ELLISTAT



Select monitoring criteria carefully

In a workshop, a part generally has numerous characteristics.

But it's impossible to monitor all of them using control charts!

👉 Here are the key rules for selecting them correctly:

- ◆ The criterion should be indicative of the product's quality.
- ◆ Control charts should be the only process management tool and should not overlap with other systems.

Therefore, the sampling frequency required by the criterion must be compatible with the completion of the control charts.

- ◆ The selected criterion should preferably be controllable, meaning that, in the event of a deviation, the operator must be able to bring it back within acceptable limits.



Automating the completion of control charts

Once control charts have been implemented, they should become the only tool for managing the process.

However, as the frequency of inspections increases, manual data entry quickly becomes a bottleneck.

➡ The solution: automate data entry and processing.

This is the best way to improve responsiveness, reliability, and efficiency.



Implementing SPC software

With today's digital tools, not computerizing your control charts would be a missed opportunity!

Here are 3 good reasons to switch to software 🙋

- ◆ Integrated monitoring: your charts become part of a global production management system.
- ◆ Time savings: the inspection frequency is now too high to be handled manually.
- ◆ Efficiency: there are too many parameters to monitor to manage everything on paper.

💡 If you'd like to discover an SPC software, we know one that's very easy to use 😊




Recalculate the limits

A common issue encountered when applying control charts concerns the recalculation of limits.

💡 Remember: the limits depend exclusively on the short-term variability of the process.

👉 If the process is stable, the limits do not change.

👉 Recalculation should only be performed if the short-term variability actually changes.



Sustaining the SPC approach over time

Implementing an SPC approach is one thing.
Maintaining it over time is another.

Too many companies end up falling into the cycle:
implementation ▶ loss of momentum ▶
reimplementation... A costly process for the
organization.

Here are some levers to firmly embed the approach
in the long term:

- ◆ Establish a steering committee
- ◆ Train personnel not only on the tools but also on quality culture
- ◆ Follow the method consistently
- ◆ Monitor capability indices and take action in case of deviations
- ◆ Implement an audit system to prevent drift
- ◆ Share successes to keep motivation high