

Magnetic PDMS film
Adhesive
Crease
Pre-stretched elastomer
Bonding sites
Release prestrain
S1 (one center peak)
S2 (one side peak)
Magnetic actuation
S3 (two peaks)
S4 (twisted two peaks)