
A




B Cases at strain=15%


(i) n_{crease} = 0




(ii) n_{crease} = 2



(iii) n_{crease} = 3



(iv) n_{crease} = 4




(v) n_{crease} = 7




C Cases at n_{crease} = 3


(vi) strain = 8%



(vii) Strain = 18%



(viii) Strain = 24%



(ix) Strain = 34%

