
Electrical Design: System Circuit Diagram



System State Machine

Button Press

State 0 : Waiting for Button Press, Polling



Button Press

State 1 : Start Timer1 to enable encoder readings



Default

State 2 : PI Control to Move Motor until desired reference angle



State 5 : Outputting and Reading Hall Sensor Data



Default

State 4 : Start MsTimer2 for Hall Sensor Reading



Button Press

State 3 : Waiting for Button Press, Polling

Error (Reference Angle – Encoder Reading) < ±2 degree