Feed Homing	Sort Homing	Feed Prox Sensor	Feed Motor	Sort Motor	Air Drop	Camera
Signal Gnd 5v+	Signal Gnd 5v+	Signal Gnd 12V+	A2 A1 B1 B2	A2 A1 B1 B2	12V+ Gnd	Fan Light 2nd Cond Cond Cond Cond Cond Cond Cond Co