		Feed Homing Sort Homing Feed Prox Sort Mo		rt Moto	r	Feed Motor			Air Drop	Camera			
Camera USB	Gnd	Signal Gnd 5V+	Signal Gnd 5V+	Signal <mark>Gnd</mark> 12V+	`	A1 B1	B2	A2	, ш	B2	12V+ Gnd	Fan Gud	Light Pug