


BUDDERFLY INVOICE SUBMISSION GUIDLELINES – VERSION 2

1. Invoices or Credit Memos [CM] should be sent **ONLY 1 time** to billing@eprocessor.budderfly.com
 - a. Please note that above email address is for Invoice Submission/ Credit Memos only.
 - b. Do not re-send an invoice to this email address unless instructed by Budderfly.
2. Reminders, Account Statements, Billing Inquires, and correspondence should be sent to accounts_payable@budderfly.com
3. Each Budderfly Work Order # Requires a Separate Invoice.
4. All Invoices Must include the below requirements to be processed or Invoice will be **REJECTED**.
 - a. **Invoice Date** – Must be dated within 10 days of Date Invoice Emailed to Budderfly.
 - b. Invoice Amount
 - c. Budderfly Work Order # or Budderfly Purchase Order #
 - d. Budderfly Site ID – i.e., SUBW-XXXX, MCD-XXXX
 - e. Date of Service Provided – This is not Invoice Date, but actual date(s) work took place.
 - f. Description of Service Provided
5. Invoices for any **Install or Service Call** – See additional below Requirements.
 - a. **Equipment Cost** must be Detailed if it is more than \$300.
 - b. **Labor Cost** must be Detailed – we will not accept a Total Labor Cost only.
 - c. Install Invoices may have Detail based on Executed MSA agreed pricing.
 - d. Example below of Detail Required

Service Date	Quantity (Hours or Material)	Description	Price (Hourly Rate or Unit Material Cost)	Total (Hourly Cost or Material Cost)
2.2.2025	14.00	Standard Time	\$100.00	\$1,400.00
2.2.2025	1.00	Electrical Materials - Assorted	\$36.75	\$36.75
2.2.2025	1.00	Control Board	\$3,500.00	\$3,500.00
2.2.2025	3.00	Nitrogen 40	\$22.00	\$66.00
2.2.2025	1.00	Welding Materials - Assorted	\$75.00	\$75.00
2.2.2025	15.00	R410A	\$45.00	\$675.00
2.5.2025	5.00	Standard Time	\$100.00	\$500.00
2.5.2025	6.00	Overtime	\$150.00	\$900.00

6. If Invoice [Service or Install] has had a **Quote** Approved prior by Budderfly PM, above Detail is still Required on Invoice – Total Quote Amount only will be Rejected.
7. Invoices related to **HVAC Service Call** are **Required** to include **Serial #** and **Make** of RTU(s) associated with Invoice Activity. Invoices missing this data will be Rejected.
 - a. HVAC Service Call Invoice are Required to adhere to #5 Above for detail.
 - b. If HVAC Warranty Process is Bypassed and you Invoice Budderfly Part, good potential for Invoice to be Rejected. We expect all Contactor's to follow process for obtaining Part from certified dealer and invoice reflects Part as \$0 - covered under Warranty.
8. Invoices related to **HVAC Installation**
 - a. HVAC Installation Invoices - **Required** to include **Serial #** and **Make** of RTU(s) associated with Invoice Activity. Invoices missing this data will be Rejected.
 - b. HVAC Installation Invoices – Invoice must contain line item showing date HVAC Post Install Survey was sent to Budderfly. We will not accept invoices for payment prior to receipt of Survey.
 - c. Structural Engineer Invoices – any cost associated to Structural Engineering is required to be Invoiced on Separate Invoice and contain line item showing date Engineering Report was sent to Budderfly. We will not accept invoices for payment prior to receipt of Report.

- d. HVAC Temp Cooling - any cost associated with Temp Cooling is required to be Invoiced on Separate Invoice and contain below data points -
 - i. Temp Cooling Work Order #
 - ii. Number of Temp Cooling Units
 - iii. Months Covered of Temp Cooling
 - iv. Cost Per Temp Cooling Unit Per Month
 - e. HVAC Storage – any cost associated to Storage of RTUs or Curbs are required to be Invoiced on Separate Invoice and contain below data points -
 - i. Budderfly Site ID of RTUs
 - ii. Storage Work Order
 - iii. Number of RTUs
 - iv. Number of Curbs
 - v. Months Covered
 - vi. Cost Per Month
 - f. Contractor Sourced RTU(s) and/or Curbs – any cost associated to RTUs or Curbs Procured by Contractor are required to be Invoiced on Separate Invoice from RTU Install Invoice and contain below data points -
 - i. Cost Per RTU
 - ii. Make
 - iii. Model
 - iv. Serial
 - v. Tonnage
 - vi. # of Curbs
 - vii. Cost Per Curb
9. Credit Memo [CM] Requirement.
- a. Each CM Must Contain Budderfly Site ID, Work Order Number, Reason for Issue
 - b. Each CM can only be for 1 Budderfly Work Order Number – cannot combine multiple CM into 1 CM.
 - c. Submission of CM is to billing@eprocessor.budderfly.com
 - d. Once CM is processed by Budderfly, AP Team will share what Open Invoice(s) CM was applied to so you can update your records.
 - e. We do not allow any Credit to be included in reducing a future invoice – we **MUST** receive actual CM as detailed above.
10. **Rejected Invoices** – When Budderfly Rejects an Invoice, an email is sent to the Contractor to alert and provide insight into Rejection reason. Any questions on the email address we have on file for you can be answered by reaching out to accounts_payable@budderfly.com. Please note that the email address sending Rejection is payments@budderfly.com and this is an **Un-Monitored email box**.
- a. Always read full text in Rejection email as an Invoice could be Rejected for more than (1) Missing Requirement. All need to be updated to resubmission.
 - b. When Resubmitting a Rejected invoice, you **MUST** update the **Invoice Date** to meet the requirement noted above in Section 4 – a.
 - c. Example of Rejection email – *next page*



Any questions on any of the above information can be sent to accounts_payable@budderfly.com and we will be happy to answer your inquiry.