





USB




Calibration POGO




CV In/Out




Audio Out



RP2040 and friends



Input MUX



Power

