








Every connected symbol pin has one explicit wire stub. Only hierarchical labels cross functional= sheet boundaries.







Every connected symbol pin has one explicit wire stub. Only hierarchical labels cross functional= sheet boundaries.

