
(a) ray view: load factor = reach
$\mathcal{X}^+$
$\overline{s}$
C slip
$s^\star$
$\underline{s}$
B undecided
A hold
$\mathcal{X}^-$
τ/L_0
f_x
(b) dual view: tightest half-plane
τ/L_0
f_x
(c) decision vs measurement
true capacity
$\mathcal{M}_0$
$\mathcal{M}_F$ 4x4
$\mathcal{M}_T$ 4x4
$\mathcal{M}_T$ 16x16
0
1
2
3
demanded load / true capacity $s^\star$
true wrench set $\mathcal{X}(\nu^\star)$
possible set $\mathcal{X}^+$ (solid)
guaranteed set $\mathcal{X}^-$ (dashed)
half-plane of $\mathcal{X}^+$, tightest one thick
half-plane of $\mathcal{X}^-$
cut of the ray by a half-plane
$\underline{s}$ (certified)
$s^\star$ (true)
$\overline{s}$ (upper)
hold
undecided
slip