
Safety Points

- 1. The three most important rights of a worker are:
 - Right to know
 - Right to participate
 - Right to refuse
- 2. If working alone, designate someone to 'check in' with you periodically.
- 3. Hazard controls in order from most to least effective:
 - Eliminate
 - Substitution
 - Engineering controls
 - Administrative controls
 - Personal protective equipment
- 4. WHMIS symbols:



- A: Compressed gases
- B: Flammable/combustible
- C: Oxidizing materials
- D: Materials causing immediate and serious toxic effects
- E: Materials causing other toxic effects
- F: Biohazardous infectious materials
- G: Corrosive materials
- H: Dangerously reactive materials
- 5. Workplace labels must include:
 - Name of the chemical
 - Safe handling measures
 - Reference to MSDS

- 6. Clothes that must be worn: long pants and close-toed shoes.
- 7. The material safety data sheet, MSDS, is a detailed document that describes the chemicals being used:
 - Hazardous ingredients
 - Preparation information
 - Product information
 - Physical data
 - Reactivity data
 - Preventative measures
 - Fire or explosion hazard data
 - Toxicological properties
 - First-aid measures
- 8. Important locations in or near the lab:
 - The spill kit is located beside the lab computer.
 - The nearest emergency pull station is located outside of the lab, across the hall.
 - The safety shower is located right beside the main door of the lab.
 - The eye wash station is located beside the central sink.
 - The first-aid kit is located beside the lab computer.