## **COMMONWEALTH OF AUSTRALIA**

## **Copyright Regulations 1969**

#### Warning

This material has been reproduced and communicated to you by or on behalf of *The Charles Darwin University* pursuant to Part VB of the *Copyright Act 1968* (the Act). The material in this communication may be subject to copyright under the Act. Any further reproduction or communication of this material by you may be the subject of copyright protection under the Act.

Do not remove this notice

# DSP First

Laboratory Exercise #2

## Introduction to Complex Exponentials

The goal of this laboratory is gain familiarity with complex numbers and their use in representing sinusoidal signals as complex exponentials.

#### 1 Overview

Manipulating sinusoid functions using complex exponentials turns trigonometric problems into simple arithmetic and algebra. In this lab, we first review the complex exponential signal and the phasor addition property needed for adding cosine waves. Then we will use MATLAB to make plots of phasor diagrams that show the vector addition needed when combining sinusoids.

#### 1.1 Complex Numbers in Matlab

MATLAB can be used to compute complex-valued formulas and also to display the results as vector or "phasor" diagrams. For this purpose several new functions have been written and are available on the *DSP First CD-ROM*. Make sure that this toolbox has been installed by doing help on the new M-files: zvect, zcat, ucplot, zcoords, and zprint. Each of these functions can plot (or print) several complex numbers at once, if the input is formed into a vector of complex numbers. The following example will plot five vectors all on one graph:





Here are some of Matlab's complex number operators:

conj	Complex conjugate
abs	Magnitude
angle	Angle (or phase) in radians
real	Real part
imag	Imaginary part
i,j	pre-defined as $\sqrt{-1}$
x = 3 + 4i	i suffix defines imaginary constant
exp(j*theta)	Function for the complex exponential $e^{j\theta}$

Each of these functions takes a vector (or matrix) as its input argument and operates on each element of the vector.



Finally, there is a complex numbers drill program called:

#### zdrill

which generates complex number problems and tests your answers. Please spend some time with this drill since it is very useful in helping you to get a feel for complex arithmetic.

When unsure about a command, use help.

#### 1.2 Sinusoid Addition Using Complex Exponentials

Recall that sinusoids may be expressed in the form:

$$x(t) = A\cos(2\pi f_0 t + \phi) = \Re\left\{Ae^{j\phi}e^{j2\pi f_0 t}\right\}$$
(1)

Consider the sum of cosine waves given by (2)

$$x(t) = \sum_{k=1}^{N} A_k \cos(2\pi f_0 t + \phi_k)$$
 (2)

where each cosine waves in the sum has the same frequency,  $f_0$ . This sum is difficult to simplify using trigonometric identities, but it reduces to an algebraic sum of complex numbers when solved using complex exponentials. This is the *Phasor Addition Rule* presented in the text. A summary of the phasor addition rule using the complex exponential representation of the cosines (1) is:

$$x(t) = \Re\left\{\sum_{k=1}^{N} Z_k e^{j2\pi f_0 t}\right\}$$
(3)

$$= \Re e \left\{ \left( \sum_{k=1}^{N} Z_k \right) e^{j2\pi f_0 t} \right\} \tag{4}$$

$$= \Re\left\{Z_s e^{j2\pi f_0 t}\right\} \tag{5}$$

$$= A_s \cos(2\pi f_0 t + \phi_s) \tag{6}$$

where

$$Z_k = A_k e^{j\phi_k} \tag{7}$$

and

$$Z_s = \sum_{k=1}^N Z_k = A_s e^{j\phi_s} \tag{8}$$

We see that the sum signal x(t) is a single sinusoid and it is periodic with period  $T_0 = 1/f_0$ .

#### 1.3 Harmonic Sinusoids

There is an important extension where x(t) is the sum of N cosine waves whose frequencies  $(f_k)$  are all multiples of one basic frequency  $f_0$ .

$$f_k = k f_0$$
 (HARMONIC FREQUENCIES)

The sum of N cosine waves given by (2) becomes

$$x(t) = \sum_{k=1}^{N} A_k \cos(2\pi k f_0 t + \phi_k) = \Re \left\{ \sum_{k=1}^{N} Z_k e^{j2\pi k f_0 t} \right\}$$
 (9)

This particular signal x(t) is also periodic with period  $T_0 = 1/f_0$ . The frequency  $f_0$  is called the fundamental frequency, and  $T_0$  is called the fundamental period.

## 2 Warm-up

The instructor verification sheet is at the end of this lab.

#### 2.1 Complex Numbers

To exercise your understanding of complex numbers, do the following:

- (a) Define  $z_1 = -1 + j0.3$  and  $z_2 = 0.8 + j0.7$ . Enter these in MATLAB and plot them with zvect, and print them with zprint.
- (b) Compute the conjugate  $z^*$  and the inverse 1/z for both  $z_1$  and  $z_2$  and plot the results. In MATLAB, see help conj. Display the results numerically with zprint.
- (c) Compute  $z_1 + z_2$  and plot. Use zcat to show the sum as vectors head-to-tail. Use zprint to display the results numerically.
- (d) Compute  $z_1z_2$  and  $z_1/z_2$  and plot. Use the **zvect** plot function to show how the angles of  $z_1$  and  $z_2$  determine the angles of the product and quotient. Use **zprint** to display the results numerically.
- (e) Work a few problems on the complex number drill program. To start the program simply type zdrill.

Instructor Verification (separate page)

#### 2.2 Sinusoidal Synthesis with an M-File

Write an M-file that will synthesize a waveform in the form of (2). Write the function without using for loops. Take advantage of the fact that matrix-vector multiplication computes a sum of products. For example,

$$\mathbf{c} = \mathbf{A}\mathbf{b} \qquad \Longrightarrow \qquad c_n = \sum_{k=1}^{L} a_{nk} b_k \tag{10}$$

where  $c_n$  represents the  $n^{\text{th}}$  element of the vector  $\mathbf{c}$ ,  $a_{nk}$  is the element in the  $n^{\text{th}}$  row and  $k^{\text{th}}$  column of the matrix  $\mathbf{A}$ ,  $b_k$  is the  $k^{\text{th}}$  element of the vector  $\mathbf{b}$ , and L is the number of columns in  $\mathbf{A}$ . The first few statements of the M-file should look like

```
function
                xx = sumcos(f, Z, fs, dur)
          Function to synthesize a sum of cosine waves
%SUMCOS
  usage:
%
       xx = sumcos(f, Z, fs, dur)
%
        f = vector of frequencies
%
               (these could be negative or positive)
%
        Z = vector of complex exponentials: Amp*e^(j*phase)
%
       fs = the sampling rate in Hz
%
      dur = total time duration of signal
%
%
     Note: f and Z must be the same length.
              Z(1) corresponds to frequency f(1),
%
%
              Z(2) corresponds to frequency f(2), etc.
```

The MATLAB syntax length(f) returns the number of elements in the vector f, so we do not need a separate input argument for number of frequencies. On the other hand, the programmer should provide error checking to make sure that the lengths of f and Z are the same. It is possible

(although not required) to complete this function in a single line. For some hints, please refer to the review of matrix multiplication in the *Using Matlab* Appendix of the text.

In order to use this M-file to synthesize periodic waveforms, you would simply choose the entries in the frequency vector to be integer multiples of the desired fundamental frequency. Try the following test and plot the result.

```
xx = sumcos([20], [1], 200, 0.25);
xx = sumcos([20 40], [1 1/2], 200, 0.25);
xx = sumcos([20 40 60 80], [1 -1 1 -1], 200, 0.25);
```

Instructor Verification (separate page)

### 3 Exercises: Complex Exponentials

#### 3.1 Representation of Sinusoids with Complex Exponentials

In MATLAB consult help on exp, real and imag.

- (a) Generate the signal  $x(t) = Ae^{j(\omega_0 t + \phi)}$  for A = 3,  $\phi = -0.4\pi$ , and  $\omega_0 = 2\pi(1250)$ . Take a range for t that will cover 2 or 3 periods.
- (b) Plot the real part versus t and the imaginary part versus t. Use subplot(2,1,i) to put both plots in the same window.
- (c) Verify that the real and imaginary parts are sinusoids and that they have the correct frequency, phase and amplitude.

#### 3.2 Verify Addition of Sinusoids Using Complex Exponentials

Generate four sinusoids with the following amplitudes and phases:

```
x_1(t) = 5\cos(2\pi(15)t + 0.5\pi)
x_2(t) = 5\cos(2\pi(15)t - 0.25\pi)
x_3(t) = 5\cos(2\pi(15)t + 0.4\pi)
x_4(t) = 5\cos(2\pi(15)t - 0.9\pi)
```

- (a) Make a plot of all four signals over a range of t that will exhibit approximately 3 cycles. Make sure the plot includes negative time so that the phase at t = 0 can be measured. In order to get a smooth plot make sure that your have at least 20 samples per period of the wave.<sup>1</sup>
- (b) Verify that the phase of all four signals is correct at t = 0, and also verify that each one has the correct maximum amplitude. Use subplot(3,2,i) to make a six-panel subplot that puts all of these plots on the same page.
- (c) Create the sum sinusoid via:  $x_5(t) = x_1(t) + x_2(t) + x_3(t) + x_4(t)$ . Make a plot of  $x_5(t)$  over the same range of time as used in the last plot. Include this as the lower panel in the plot by using subplot (3,1,3).

<sup>&</sup>lt;sup>1</sup>If you have already studied sampling in Chapter 4, then this requirement of 20 samples per period amounts to considerable oversampling.

- (d) Measure the magnitude and phase of  $x_5(t)$  directly from the plot. In your lab report, include this plot with sufficient annotation to show how the magnitude and phase were measured.
- (e) Now do some complex arithmetic; create the complex amplitudes corresponding to the sinusoids  $x_i(t)$ :

$$z_i = A_i e^{j\phi_i} i = 1, 2, 3, 4, 5$$

Give the numerical values of  $z_i$  in polar and Cartesian form.

- (f) Verify that  $z_5 = z_1 + z_2 + z_3 + z_4$ . Show a plot of these five complex numbers as vectors. Use the MATLAB functions zvect, zcat and zprint discussed in the Warm-up.
- (g) Relate the magnitude and phase of  $z_5$  to the plot of  $x_5(t)$ .

When unsure about a command, use help.

#### 4 Periodic Waveforms

Each of the following waveforms can be synthesized with a simple call to the function sumcos. Plot a short section of the signal to observe its characteristic shape.

Note: It is important to have a sampling rate that is at least twice as high as the highest frequency component in your signal. This is an important fact about sampling that will be discussed in Chapter 4, but for this lab you should just choose a very large number for  $f_s$  to get a smooth plot.

(a) Try your sumcos M-file with the fundamental  $f_0 = 25$  Hz,  $f_k = kf_0$ , and

$$Z_k = \begin{cases} \frac{j}{k} & k \text{ an odd integer} \\ 0 & k \text{ an even integer} \end{cases}$$
 (11)

Specify the duration to get three periods of the waveform.

Make plots for three different cases: N = 5, 10, and 25 (where N is the number of cosines). Use a three-panel subplot to show all three signals together. Explain how the period of synthesized waveform is related to the fundamental frequency.

Explain what happens as  $N \to \infty$ . What wave shape do the plots converge to? Although the waveshape is converging to a simple form, it is not perfect. Describe any unusual features in the converging waveform as  $N \to \infty$ .

- (b) It is informative to listen to these signals as a different number of coefficients are added. Repeat the synthesis from part (a) with  $f_0 = 1$  kHz and listen to the cases where N = 1, 2, 3, 4, 5 and 10. You need about 1 second of the signal to hear differences. When using sound(x, fs), the sampling frequency should be very high to avoid aliasing effects (discussed in Chapter chap:sampling).
- (c) Now try the coefficients

$$Z_k = \begin{cases} \frac{j(-1)^k}{2\pi k} & k \text{ an integer} \end{cases}$$
 (12)

Choose the fundamental frequency to be  $f_0 = 25$  Hz. Compute the signal for three cases: N = 5, 10, and 25, and plot all three functions together with a three-panel subplot. What waveshape is approximated with this sum of cosines as  $N \to \infty$ ? Explain how the period of synthesized waveshape is related to the fundamental.

## Lab 2 Instructor Verification Sheet

Staple this page to the end of your Lab Report.

Name:	Date:
Part 2.1 Complex number exercises and drill:	
Verified:	
Part 2.2 Complete sumcos.m and plot test wavefo	orms:
Verified:	