

APPENDIX: 1

SAFETY & SECURITY BULLETIN (U-SMS-09)

Revision: Original

Date: 7/1/2015

Bulletin No: 17-014
18-004


Date: 28/Nov/17
Reissued 6/Mar/18

SUBJECT: RAMP procedures reminder

APPLICABLE TO: ALL RAMP PERSONNEL

When assign to work a flight using a bulk loaded aircraft such as Viva Colombia, XTRA, SWIFT, ARUBA, World Atlantic you must insure that

- | |
|--|
| 1- No GSE that needs to mate with the aircraft does not touches the fuselage. They must leave 2" gap |
| 2- Make sure that all nets and or locks are set, even if the bin is empty |
| 3- Make sure that the 2' gap between the ceiling and the last bag are respected/ follow |
| 4- YOU use a guide person when approaching the Aircraft with a piece of GSE |
| 5- YOU use the appropriate PPE |
| 6- No GSE is inside the ERA, when marshalling in or pushing aircraft back. Including wheel chocks |



PREPARED BY:

Safety Department