



APPENDIX: 1

SAFETY & SECURITY BULLETIN (U-SMS-09)

Revision: Original

Date: 7/1/2015

Bulletin No: 18-012

Date: 16/Oct/18
Reissued

SUBJECT: RAMP SAFETY

APPLICABLE TO: ALL RAMP PERSONNEL

Section J of ULTRA GOM J.4 details the proper ramp safety procedures when performing aircraft towings

GSE required

1 Push tractor

1 Tow bar

1 by pass pin

1 set of head sets

Personnel required

1 driver

2 wing walkers

Don't allow this happen to you. Always use wing walkers

JACDEC @JacdecNew · 34m

KLM Boeing 747-400 (PH-BFN) took serious damage to its #4 engine cowlings when it was hit by a high-loader during parking at Amsterdam Schiphol Intl Airport (AMS, EHAM). There were no injuries reported. bit.ly/2RQRuDx



1 19 15

Remember you SMS training report any unsafe acts, or hazard conditions to you supervisor or manager or anonymously to safety@ultravi.com

Be SAFE follow all ramp safety rules and company SOP

PREPARED BY:

Safety Department