



APPENDIX: 1

SAFETY & SECURITY BULLETIN (U-SMS-09)

Revision: Original

Date: 7/1/2015

Bulletin No: 18-005
19-023


Date: 22-Mar-18
Reissued 27-Dec-19

SUBJECT: RAMP procedures reminder

APPLICABLE TO: ALL RAMP PERSONNEL

Remember during arrival and after you have finish working a flight all GSE MUST BE placed in their correct parking area. **Behind the containment line. The ERA must be clear of any GSE this includes chocks and cones ULTRA GOM J.1.2/ IGOM3.1.2.3**

Containment line ERA boundary/ Línea de contencion frontera del ERA



Recuerde mientras la aeronave se acerca a la puerta y después que se termina el servicio y se va a empujar desde la puerta, **NO PUEDE HABER NINGUN EQUIPO DENTRO DEL ERA**, todo debe estar estacionado/ posicionado detrás de la línea de contención. Esto incluye calzos y conos. ULTRA GOM J.1.2// IGOM 3.1.2.3

PREPARED BY:

Safety Department