



APPENDIX: 1

SAFETY & SECURITY BULLETIN (U-SMS-09)

Revision: Original

Date: 7/1/2015

Bulletin No: 22-019

Date: 5/May/22

Reissued

SUBJECT: RAMP SAFETY

APPLICABLE TO: ALL RAMP PERSONNEL

Section J of ULTRA GOM J.3.12 and J.4 details the proper ramp safety procedures when operating GSE inside the ERA

Don't allow this happen to you. Always pay attention to the task at hand




If the bridge control module is forward and the rail is in the up position it will hit the aircraft



Remember

- 1- Approach the aircraft at 3mph
- 2 Perform 3 brake check stops
- 3- Use a guide person
- 4- Make sure that the control module is all the way back
- 5 Ensure that the forward control module rail is down



Remember you SMS training report any unsafe acts, or hazard conditions to you supervisor or manager or anonymously to safety@ultravi.com

Be SAFE follow all ramp safety rules and company SOP

PREPARED BY:

Safety Department
