



ULTRA AVIATION SERVICES, INC.

General Operations Manual

APPENDIX: 1

SAFETY & SECURITY BULLETIN (U-SMS-09)

Revision: Original

Date: 7/1/2015

Bulletin No: 18-013

Date: 18/Oct/18

SUBJECT: FOD PREVENTION

APPLICABLE TO: ALL ULTRA SERVICE AGENTS

IF YOU SEE, DO NOT IGNORE IT, PICK IT UP AND DISPOSED OF IT CORRECTLY

Definition

FOD: Foreign Object Debris, objects that are not a normal part of an aircraft

FOD: Foreign Object Damage cause by debris

DEBRIS: Garbage, could be natural, metal, man made

COST: Millions of dollars and possible lost of lives


Remember when working in the AOA (RAMP) if you see any type of debris, do not ignore it, pick it up and disposed of it in the FOD barrel that is assigned to the area.

Keep your assigned GSE clear of any garbage (FOD)

If the barrel is full call MDAD at 305- 876-7311 and ask for a pick up

YOU can also call MDAD at 305-876-7486 and report any FOD issues on the AOA

Remember FOD walk in accordance to our GOM section J are performed (A) before the aircraft arrives (B) During the operation, (C) After the push back.....NEVER LEAVE A GATE AREA WITH DEBRIS ALL OVER, DO YOUR JOB AND PICK IT UP



DO NOT IGNORE IT

DO YOUR DUTY AND PICK IT UP

Remember you SMS training report any unsafe acts, or hazard conditions to you supervisor or manager or anonymously to safety@ultravi.com

PREPARED BY:

ULTRA SAFETY DEPARTMENT