SAFETY - WORK GEAR AND PERSONAL EFFECTS F0-138

OVERVIEW

The purpose of this document is to ensure that you are aware of your responsibility to supply work clothing and personal effects. Hy-Tech job locations vary and so do the weather conditions and we'd like to ensure that you are prepared for all situations.

It is important that you closely review this information prior to your departure as you are required to **supply and wear** the appropriate work clothing and gear. Employees who do not have the required work gear will be subject to Hy-Tech's disciplinary process. Hy-Tech will work with the employee to have the required work gear sent to the job site at the employee's expense.

Hy-Tech will provide safety glasses, hard hat, and ear plugs. Refer to POL-02C Employee Policy; Field (Canadian Employees) to verify other items eligible for reimbursement.

WINTER JOB CHECKLIST (MUST HAVE)

- ☐ 1 pair of -70 to -100◦C winter boots. CSA Approved Safety Toe and Plate (i.e., Baffin - Derrick)
  TIP: -40◦C Dunlop footwear does not provide sufficient insulation when temps drop below -10◦C
- ☐ Insulated coverall or bibs. **See Ontario Regulations below if working in Ontario.**
- ☐ Insulated jacket. **See Ontario Regulations below if working in Ontario.**
- ☐ Personal ski gloves or gauntlet gloves for travel to and from worksite
- ☐ Long Johns
- ☐ Neck warmer and toque or Balaclava

WINTER JOB CHECKLIST (OPTIONAL)

- ☐ Bama Socks or Thermal Socks
- ☐ Winter rated sleeping bag (-25◦C or colder) **Refer to crew change sheet for verification**

  TIP: A mummy bag rated for -7◦C will not be adequate during extreme freezing conditions or during a fuel shortage or power outage.

YEAR-ROUND JOB CHECKLIST (MUST HAVE)

- ☐ 1 pair of work boots that meet the following requirements.
  - → CSA approved steel toe
  - → Steel Shank
  - → Recommended: Leather Hiker style work boots for Heli Jobs
  - → Recommended: Metatarsal protection **(Internal Met Guard)**
    NOTE: Metatarsal Guard is required for work underground- Rubber boot style preferred. See boot diagram below.
    NOTE: Vale (Thompson) – Vale requires that all workers on site have an internal MET Guard boot. External MET Guard will not be accepted.
- ☐ Minimum 1 set of waterproof slickers that fit over your work gear. **See Ontario Regulations below.**
  NOTE: Wet rod pulls occur in the winter as well as in the summer.
- ☐ Coveralls with reflective stripes. New employees should come prepared with one pair. Hy-Tech will provide coveralls when your size is confirmed. **See Ontario Regulations below. (NOTE: Vale (Thompson) If you choose to not wear coveralls a Hi-Vis Shirt/Jacket and Hi-Vis Pants must be worn.)**
- ☐ Prescription Safety Glasses if required.

PERSONAL EFFECTS CHECKLIST (MUST HAVE)

- ☐ Towel(s).
- ☐ Shampoo, soap, etc.
- ☐ Care card / Health card.
- ☐ Major Credit Card (in case there are circumstances that would require a major credit card while traveling to a job i.e. securing a hotel room).
- ☐ Cash (bring an adequate cash supply in case of an emergency).
- ☐ Prescription Drugs or Medication.
- ☐ Medic Alert Bracelet (if you have any special medical needs).
- ☐ Epi-pen (Epinephrine auto-injector) if you have any known severe allergies.
- ☐ Day pack.
- ☐ Flip flops (for community showers).
- ☐ Water Canteens (enough drinking water for your shift).

PERSONAL EFFECTS CHECKLIST (OPTIONAL)

- ☐ Cigarettes (if a Smoker), ensuring an adequate supply until turnaround.
- ☐ Alarm clock.
- ☐ Watch.
- ☐ Leg/Calf compression socks (prevents chafing when wearing rubber boots).
- ☐ Sunscreen in the summer.
- ☐ Camp shoes. **Refer to crew change sheet for verification or contact your scheduling representative.**
- ☐ Sleeping bag and pillow. **Refer to crew change sheet for verification or contact your scheduling representative.**

ONTARIO REGULATIONS-DUSK UNTIL DAWN AND UNDERGROUND CHECKLIST

Note: On July 1, 2016, subsection 262 (2) of the Regulation is revoked and the following substituted (See O.Reg.265/15, s.18)

18. Subsection 262 (2) of the Regulation is revoked and the following substituted:

(2) Every worker in an underground mine shall wear,

- (a) high visibility safety apparel that makes the worker visible to others in the workplace and that meets the requirements set out in subsection (3); and
- (b) retro-reflective material applied to the front, back and sides of head gear.

(3) High visibility safety apparel must meet the following requirements:

1. It shall be made of fluorescent or bright-coloured background material.
2. It shall have retro-reflective striping that,
   - i. is located on the outside of the garment,
   - ii. measures at least 50 mm in width,
   - iii. completely encircles the waist, each arm and each leg below the knee,
   - iv. is arranged in two vertical lines on the front of the garment, extending over the shoulders and down to the waist, and
   - v. is arranged in the form of an "X" on the back of the garment, extending from the shoulders and down to the waist.

(4) All high visibility safety apparel and all retro-reflective material on head gear must be maintained in good condition so that they adequately visually identify a worker.

Note: On July 1, 2016 subsection 263 (2) of the Regulation is revoked and the following substituted (see O.Reg.265/15, s.19(1))

(2) Subject to subsection (3), between sunset and sunrise, every worker on the surface shall wear,

(a) high visibility safety apparel that makes the worker visible to others in the workplace and that meets the requirements set out in subsection 262 (3); and

(b) retro-reflective material applied to the front, back and sides of head gear.

(3) A worker is not required to comply with subsection (2) if the worker is in a booth, vehicle cab or another protective enclosure or if a worker is provided with fixed lighting that enables the worker to be seen (see O.Reg.291/02, s.8)


Note: On July 1, 2016 subsection 263 of the Regulation is amended by adding the following subsection (see O.Reg.265/15, s.19(2))

(4) All high visibility safety apparel and all retro-reflective material on head gear must be maintained in good condition so that they adequately visually identify a worker.



NOTE: Hy-Tech is more than willing to support the delivery of personal effects to camp if you end up working longer than planned, or have something unexpected come up where you need personal items sent to you. If you arrange for a package to be delivered to any of our Hy-Tech offices, we will make sure that you receive it.

METATARSAL BOOT DIAGRAM











Feel free to contact the safety team at safety@hy-techdrilling.com if you would like assistance in finding appropriate work gear or if you have any other questions.