






① SHAFT BODY
SCALE 1:1




② LOWER FORK
SCALE 1:1




③ UPPER FORK
SCALE 1:1


- NOTES:
1. ALL DIMENSIONS ARE IN INCHES
 2. TOLERANCES:
X.XX=±.01
X.XXX=±.005
ANGLES=±2°
 3. INSIDE TOOL RADIUS .02 MAX
 4. BREAK SHARP EDGES .01 MAX
 5. $\sqrt{63}$ FAO



① SHAFT BODY
SCALE 1:1




② LOWER FORK
SCALE 1:1



③ UPPER FORK
SCALE 1:1

- NOTES:
1. ALL DIMENSIONS ARE IN INCHES
 2. TOLERANCES:
X.XX=±.01
X.XXX=±.005
ANGLES=±2°
 3. INSIDE TOOL RADIUS .02 MAX
 4. BREAK SHARP EDGES .01 MAX
 5. $\sqrt{63}$ FAO

Cal Poly Mechanical Engineering ME 251 - FALL 2024	Lab Section: 11	Assignment # 8	Title: SHIFTER FORK ASSEMBLY	Drwn. By: S. ROBINSON
	Dwg. #: 6020	Nxt Asb:	Date: 11/26/24	Chkd. By: ME STAFF



ITEM NO.	QTY.	DESCRIPTION	PART NUMBER	MATERIAL
1	1	SHAFT BODY	6020-01	6061-T6 (SS)
2	1	UPPER FORK	6020-02	6061-T6 (SS)
3	1	LOWER FORK	6020-03	6061-T6 (SS)

Cal Poly Mechanical Engineering ME 251 - FALL 2024	Lab Section: 11	Assignment # 8	Title: SHIFTER FORK ASSEMBLY		Drwn. By: S. ROBINSON
	Dwg. #: 6021	Nxt Asb:	Date: 11/26/24	Scale: 1:1	Chkd. By: ME STAFF