

The green line is the most inaccesible rail on the mbta.\*

Unfortunately, there are no automatic bridge plates on any green line cars. Any passenger who uses a wheeled mobility device must request the assistance of a conductor.

This method is inconvenient for the rider, the conductor, and the rest of the passengers on board (and even possibly other trains), as the conductor must pause the trip to assist the passenger. Additionally, this process also causes impatient passengers to project their frustration on to the rider with the disability.

Automatic bridge plates are becoming an industry standard and should be implemented in the green line. The current offering diminishes the rider's experience and stifles their independence. Overall, not having automatic bridge plates only contributes the inefficiency and lackluster experience of the T.

\* To help make the green line more accessible, go to:

https://www.mass.gov/forms/contact-massdot