ISLAND MOTORCYCLE COMPANY

John Campbell #1 928 Bay St Victoria, BC

Repair Order

Invoice

Doc Number: 314164
Service Writer: Devon Schmoll
Date Printed: 08/06/2024
Date Promised: 12/08/2023
Cashier: Devon Schmoll
Cashier Date: 12/13/2023

Customer Information

Home Phone: 250-741-4404 Cell Phone: 250-741-4404

Email: jpcampbell@mrc.com

Fold Here

Summary

Approve	Decline	Unit	Job	Job Total
$\overline{\vee}$		2009 BMW F 800 GS	INSTALL NEW LEFT HEATED GRIP	\$226.99
		2009 BMW F 800 GS	INSTALL NEW REAR BRAKE PADS	\$309.49
			Job Subtotal:	\$536.48
			Misc:	\$30.75
			Job Parts Subtotal:	\$228.98
			Job Labor Subtotal:	\$307.50
			PST - 1001-1272 - 7.00%:	\$39.70
			GST - 12662 6357RT0001 - 5.00%:	\$28.36
			Total:	\$635.29
			Less Deposits:	\$0.00
			Mastercard:	(\$635.29)
			Total Due:	\$0.00

THANK YOU FOR YOUR BUSINESS!!

** VEHICLES NOT PICKED UP WITHIN 5 DAYS OF NOTIFICATION OF WORK COMPLETION WILL BE SUBJECT TO A \$25.00 PER DAY STORAGE FEE. **
WE DO NOT RETAIN TAKE OFF PARTS UNLESS REQUESTED BY CUSTOMER. PARTS MUST BE PICKED UP WITHIN 7 DAYS OR THEY WILL BE

DISPOSED OF.______ INITIAL PLEASE

NO RETURNS ON ELECTRICAL PARTS

DUE TO THE FACTORY COATING ON ALL NEW TIRES. A 'BREAK-IN' PERIOD IS REQUIRED BEFORE TIRES WILL DELIVER FULL TRACTION. ISLAND MOTORCYCLE COMPANY ACCEPTS NO LIABILITY FOR ACCIDENTS CAUSED BY IMPROPER USE DURING INITIAL WEAR PERIOD.

"I HEREBY AUTHORIZE THE REPAIR WORK HEREIN SET FORTH AND THE USE OF THE MATERIAL NECESSARY TO THE COMPLETION OF SAID REPAIR WORK. TO THE EXTENT PERMITTED BY LAW, WE ARE NOT RESPONSIBLE FOR LOSS OR DAMAGE TO THE VEHICLE OR ARTIFACTS LEFT IN VEHICLE IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE BEYOND YOUR CONTROL OR FOR ANY DELAYS CAUSED BY THE UNAVAILABILITY OF PARTS OR DELAYS IN THE SHIPMENT OF PARTS BY THE SUPPLIER OR TRANSPORTER. I HEREBY GRANT YOU AND YOUR EMPLOYEES PERMISSION TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING OR INSPECTION, "

GST # 126626357 RT0001 PST #1001-1272

Signature:		
-	-	_

Detail

Unit 2009 BMW F 800 GS F 800 GS Color:

Plate: VIN/Serial No:WB10219049ZT77875 **Odom/Hrs In:**37,759 Out:37,764

INSTALL NEW LEFT HEATED GRIP

Description:INSTALL NEW LEFT HEATED GRIP

Resolution:**Renewed left grip as requested. Connected to ISTA, cleared stored fault and verified operation of grip.

Recommend:**Advise renewing rear pads - 5% material remaining

Parts

Part #	Qty	Description	Price	Discount	Total
61317727067	1.00	HANDLE LEFT	\$151.99	\$0.00	\$151.99

Parts Subtotal

\$151.99

\$226.99

Labor

Description Technician Total Will Brydon \$75.00

Labor Subtotal

\$75.00

Job Subtotal

Approve: ☑ Decline:

INSTALL NEW REAR BRAKE PADS

Description:INSTALL NEW REAR BRAKE PADS

Resolution: Old Pads removed, caliper seized on sliding pins

Wheel removed, brake carrier and caliper removed

Caliper freed from sliding pins, cleaned and regreased pins

Wheel reinstalled with caliper and carrier, New brake pads installed

Chain tension set and tire pressure set

Test ride carried out to ensure rear brake function

Parts

Part #	Qty	Description	Price	Discount	Total
34217722884	1.00	BRAKE PADS KIT, REAR	\$76.99	\$0.00	\$76.99
			Parts Subtotal		\$76.99

Labor

Description	Technician	Total
	Zander Glidden	\$232.50
	Labor Subtotal	\$232.50
	Job Subtotal	\$309.49
	Approve: ☑	Decline: □

All Jobs Subtotal: \$536.48 **Shop Supplies:** \$30.75

PST - 1001-1272 - 7.00%: \$39.70 GST - 12662 6357RT0001 - 5.00%: \$28.36

Total:

\$635.29 **Less Deposits:** \$0.00 (\$635.29) Mastercard: \$0.00

Total Due: