

WORKERS' COMPENSATION FIELD SURVEY & RISK ASSESSMENT

Policyholder:	Phoenix Metal Alloys LLC	Survey Date:	2024-09-10
Parent Company:	Phoenix Corp	Safety Inspector:	Insp. David Miller
Policy Period:	2024-06-01 to 2025-05-31	Primary Equipment:	Grind-O-Matic 500

EXECUTIVE SUMMARY & OPERATIONAL OBSERVATIONS

Phoenix Metal Alloys LLC is currently facing chemical ventilation setbacks. An airborne sheen from aerosolized coolant and grinding mist is settling directly on the metal walkways near the primary milling line, causing extremely slippery traction underfoot. Underwriters should note that although safety shoes are mandatory, walking surfaces near the machinery present high risk.

DETAILED SAFETY AREA RISK ASSESSMENT

The following table lists the assessments and safety control levels recorded for each of the eight core Workers' Compensation hazard mitigation areas. These findings are used to calculate the account's historical and loss-weighted risk profiles.

Hazard Mitigation Area	Qualitative Assessment Rating
Lifting (Industrial Ergonomics)	ADEQUATE
Lacerations/Cut Safety	ADEQUATE
Material Loading/Unloading & Securement	ADEQUATE
Overhead Lifting Equipment	ADEQUATE
Machine Guarding & Electrical Systems Safety (LOTO)	ADEQUATE
Occupational Disease & Illness	ADEQUATE
Walking/Working Surfaces	LIMITED/INCONSISTENT
Elevated Work Surfaces	NOT APPLICABLE