

WORKERS' COMPENSATION FIELD SURVEY & RISK ASSESSMENT

Policyholder:	Titanium Alloy Specialists	Survey Date:	2025-01-15
Parent Company:	Independent	Safety Inspector:	Sarah Jenkins
Policy Period:	2025-01-01 to 2025-12-31	Primary Equipment:	Hydraulic Press Model

EXECUTIVE SUMMARY & OPERATIONAL OBSERVATIONS

Titanium Alloy Specialists maintains a pristine, safety-conscious fabrication facility. Interlocks are operational on all HydroPress-9000 stamping lines. Active air monitoring systems are functioning properly. Housekeeping is robust, with only minor dust accumulation observed on high structural steel beams, which is scheduled for routine high-reach cleaning.

DETAILED SAFETY AREA RISK ASSESSMENT

The following table lists the assessments and safety control levels recorded for each of the eight core Workers' Compensation hazard mitigation areas. These findings are used to calculate the account's historical and loss-weighted risk profiles.

Hazard Mitigation Area	Qualitative Assessment Rating
Lifting (Industrial Ergonomics)	WELL-CONTROLLED
Lacerations/Cut Safety	WELL-CONTROLLED
Material Loading/Unloading & Securement	ADEQUATE
Overhead Lifting Equipment	WELL-CONTROLLED
Machine Guarding & Electrical Systems Safety (LOTO)	WELL-CONTROLLED
Occupational Disease & Illness	WELL-CONTROLLED
Walking/Working Surfaces	ADEQUATE
Elevated Work Surfaces	WELL-CONTROLLED