

WORKERS' COMPENSATION FIELD SURVEY & RISK ASSESSMENT

Policyholder:	Vulcan Heavy Industries	Survey Date:	2024-02-18
Parent Company:	Independent	Safety Inspector:	Marcus Vance
Policy Period:	2024-01-01 to 2024-12-31	Primary Equipment:	Hydraulic Press Model

EXECUTIVE SUMMARY & OPERATIONAL OBSERVATIONS

Vulcan Heavy Industries exhibits multiple intermediate exposures. The primary welding area is cluttered with debris, and spark screens are missing, exposing neighboring walkways and metal handlers to flying hot slag and intense UV radiation. While walkways are kept clean of slip hazards, material loading docks suffer from chaotic staging of heavy alloy components.

DETAILED SAFETY AREA RISK ASSESSMENT

The following table lists the assessments and safety control levels recorded for each of the eight core Workers' Compensation hazard mitigation areas. These findings are used to calculate the account's historical and loss-weighted risk profiles.

Hazard Mitigation Area	Qualitative Assessment Rating
Lifting (Industrial Ergonomics)	ADEQUATE
Lacerations/Cut Safety	LIMITED/INCONSISTENT
Material Loading/Unloading & Securement	LIMITED/INCONSISTENT
Overhead Lifting Equipment	ADEQUATE
Machine Guarding & Electrical Systems Safety (LOTO)	ADEQUATE
Occupational Disease & Illness	LIMITED/INCONSISTENT
Walking/Working Surfaces	WELL-CONTROLLED
Elevated Work Surfaces	ADEQUATE