

AC Input and Power Supplies




Heatsink Fan Connections



Overtemperature Latches and LED Indicators



Overtemperature Comparators



Mounting Screws

+ S1 Screw_#4

+ S2 Screw_#4

+ S3 Screw_#4

+ S4 Screw_#4

Sheet: /
File: Big_Fast_Switch.sch

Title: Big Fast Switch