


Project group SS18

Development of local positioning system for a pipe-less plant



Task for the week

Select formal project leader

- -> Stephan Vette
- Think through the necessary subtasks
- Write a project plan
- Schedule the next meetings



Tasks and subtasks

- 1. Get familiar to the plant
 - Read all documentations
 - 2. Search and read literature about tracking systems
- 2. Measurement of plant performance
 - Decide on quantities (Possible or not)
 - 2. Perform measurements
 - 3. Determine the weak points
 - 4. Determine the effort needed to improve performance
- 3. Find and compare different alternatives
 - 1. Vision (passive and active components)
 - Ideas beyond





Tasks and subtasks

4. Verify

- 1. Plausibility of made decisions
- Order
- 3. Prototyping
- 4. Recheck of performance improvement

5. Conclusion

- Description of overall improvement
- Description of the limit of the new setup




Project Plan

Project SoSe18


				Period Highlight:			Plan Duration					Actual Start					% Complete								
							Actual (beyond plan)					% Complete (beyond plan)													
ACTIVITY	PLAN START	PLAN DURATION	ACTUAL START	ACTUAL DURATION	PERCENT COMPLETE	PERIC				_		_													
Get familiar with the plant	1	6	1	DUKATION	0%	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20
Find some good literature	1	2	1		0%				///////////////////////////////////////	411111111	,,,,,,,,,														
Read literature	2	4			0%	111111111																			
Measurements: Decide on quantaties	2	4			0%																				
Perform measurements	6	3			0%																				
Determine the weak points	9	1			0%																				
Effort to improve performance	9	1			0%																				
Alternatives: Ideas Vision (Passive and active)	10	1			0%																				
Alternatives: Ideas beyound	10	1			0%																				
Set up decision making matrix	11	1			0%															ĺ					
Verify: Plausability of decision	11	1			0%															ļ					
Ordering	12	1			0%																				
Prototyping	12	3			0%															į					
Recheck of performance improvement	14	2			0%																				
Conclusion: Description of the overall improvement	14	1			0%																				
Conclusion: Limits of new set up	15	1			0%																				
Activity 16					0%																				
Activity 17					0%																				
Activity 18					0%																				
						018	2018	2018	2018	2018	2018	2018	2018	018	2018	118	2018	018	2018	2018	2018	2018	2018	2018	18
						03.20	03.20	3.20			4.20	.04.20	Ġ	5.2	.05.20	5.20	5.20	.06.2018	6.20	06.20	6.20				7.20
						14.0	21.0	28.03.	04.04	11.04	18.04.	25.0	02.0	0.60	16.0	23.05.2018	30.05.	0.90	13.06.	20.0	27.06.	04.07	11.07	18.07	25.07.2018



Schedule the next meetings



Abdulrahman, Medhini



Stefan, Stephan





Until next time

- Find good literature (+ short explanation)
- Read the literature
- Start to work with the plant (understanding of code)
 - Document knowledge and explain it to the others)
- For measurements: Think about quantities

