AAE 364 Control Systems Analysis Problem Set 3

Professor Inseok Hwang School of Aeronautics and Astronautics, Purdue University Fall 2019

Issued 9/6; Due 9/13

Reading Assignment:

Class material for the Laplace Transform; Sections 1,2, 3 and 7 in Chapter 2.

Problems

1. Find the inverse Laplace transforms of the following function:

$$F(s) = \frac{4s+1}{(s+1)(s+2)^2}$$

2. Find the inverse Laplace transforms of the following function:

$$F(s) = \frac{5}{s(s^2 + \omega^2)}$$

3. Obtain the inverse Laplace transform of the following function:

$$F(s) = \frac{2e^{-s}}{s+1}$$

4. Solve the differential equation

$$\ddot{x} + 3\dot{x} + 6x = e^{-t}, \ \ x(0) = 0, \ \dot{x}(0) = 0$$

5. Solve the differential equation

$$\dot{x} + 2x = \delta(t), \ x(0-) = 0$$

6. Solve the following differential equation:

$$\ddot{x} + 2\dot{x} + 5x = 0$$
, $x(0) = 0$, $\dot{x}(0) = 3$

7. Solve the following differential equation:

$$\ddot{x} + 2\zeta \omega_n \dot{x} + \omega_n^2 x = 0, \quad x(0) = a, \ \dot{x}(0) = b$$

where a and b are constants.