

Date	Month	Location of Incident	Account/Exact Location of Incident	Brief Description of Observation	Risk Details	Immediate/Corrective & Preventive Actions	Type of Incident	Time	Open/Closed
11-03-20	26-Mar	Sheward MCF 2	RBL, MTS	The wheels of the railing on the 2nd and 3rd floors of the RBL, MTS rack are broken, and it may fall down while opening it.	The railing may fall while opening, which can cause injury to associates or damage to material.	Inform to maintenance team The damaged wheels should be repaired or replaced immediately	Near Miss	10:54:00	Close
13/03/2020	26-Mar	Sheward MCF 2	RBL	1 Associate without helmet in rack	Box fall on head and injured	Instruction was given to wear safety helmet immediately this mistake again	Unsafe Activity	10:37:00	Close
14/03/2020	26-Mar	Sheward MCF 2	RBL	1 Associate without helmet in rack	Box fall on head and injured	Instruction was given to wear safety helmet immediately this mistake again	Unsafe Activity	10:47:00	Close
16/03/2020	26-Mar	Sheward MCF 2	RBL, Electrical panel	RBL electrical panel blocked by combustible material	It may cause fire hazard and spread quickly in the area	Combustible materials were removed immediately from in front of the electrical panel	Unsafe Activity	17:29:00	Close
16/03/2020	26-Mar	Sheward MCF 2	RBL, Exit door 27 near fire bucket stand	Fire bucket stand block by material	In case of fire emergency, the fire buckets cannot be accessed immediately	The material blocking the fire bucket stand was removed immediately	Unsafe Activity	18:03:00	Close
23/03/2020	26-Mar	Sheward MCF 2	RBL, H2 rack	2 Associate without safety belt on floor	There is a risk of not being clearly visible to lift&C operators or other moving equipment, which may lead to accidents, collision, or serious injury	Both associates were immediately instructed to wear safety belts	Unsafe Activity	19:49:00	Close
23/03/2020	26-Mar	Sheward MCF 2	RBL	2 Associate without helmet in rack	Box fall on head and injured	Instructions was given to wear safety helmet immediately this mistake again	Unsafe Activity	14:24:00	Close
23/03/2020	26-Mar	Sheward MCF 2	RBL	2 Associate without helmet in rack	Box fall on head and injured	Instruction was given to wear safety helmet immediately this mistake again	Unsafe Activity	15:54:00	Close
27/03/2020	26-Mar	Sheward MCF 2	RBL	The picker were sitting on the BMS without wearing a harness.	High risk of fall from height the MHE	Instruction was given to wear safety belt immediately this mistake again	Unsafe Activity	17:42:00	Close
28/03/2020	26-Mar	Sheward MCF 2	RBL	1 Associate without helmet in rack	Box fall on head and injured	Instruction was given to wear safety helmet immediately this mistake again	Unsafe Activity	9:03:00	Close
28/03/2020	26-Mar	Sheward MCF 2	RBL	The Greenpathway to the RBL area is completely blocked	Workers may use unsafe alternate routes	remove the material	Unsafe Activity	9:23:00	Close