

SOP for PDI and Packaging of CRM Material

1. Upon receipt of the CRM ticket, upload the ticket details to the CRM group.
2. After the ticket is raised, arrange the material to be dispatched/received at the plant on priority.
3. Upon receipt of the material at the plant, conduct a Pre-Dispatch Inspection (PDI).
4. During PDI, take clear photographs of each part/component and share them in the designated WhatsApp group on priority for record and verification.
5. After successful completion of the PDI, carry out additional packaging as per the approved packaging SOP.
6. Once the packaging activity is completed, take photographs of the packed material from all relevant angles.
7. Share the packaging photographs in the designated WhatsApp group and maintain the records for future reference.
8. Ensure that all activities are completed on priority to avoid delays in CRM material dispatch.

Confidential