

Document Owner:
Yuvraj DeshmukhApproved By:
Nisha SolankiApproved Date:
27-05-2026Version:
4.0Page:
1(7)

Picking Process.

Changes since last version: Update in procedure according to M3 implementation.

1. Purpose and Scope: The context of this procedure is to describe the activities involved in picking assuring the smooth flow of material from warehouse to respective function / Area. Picked parts issue as per order to respective function / area. Scope will ensure quantity, damage free parts, painted parts, rust free parts. document picking list / station list.

2. Responsibility: The overall responsibility of ensuring the implementation and maintenance of this procedure is with Functional head. Respective functional head is responsible in his / her work area.

3. Definitions and abbreviations:

3.1. Definition and Abbreviation details:

Abbreviation	Details	Abbreviation	Details
Order number	Manufacturing order of product	Stock Zone	Material Location
Item	Part number on picking list	Delivery No.	Reference number to issue in M3
Name	Part description	Qty	Quantity to of part in picking list
MHE	Material handling equipment	PPE	Personal Protective Equipment
MO	Manufacturing Order	RO	Requisition Order
CO	Customer Order	DO	Distribution Order

3.2. Accessories required for Picking Activity as below.

PPE	Gloves, Helmet, Safety Shoes, Safety Jacket.
Stationary	Picking/BOM print copy, Pen, marker, highlighter, cutter.
Equipment's	Stacker/ forklift, pallet truck, lifting belt: - for material picking and movement.
	Pallet, foam/corrugated sheet, anti-rust oil, etc
Workforce	MHEs & Warehouse storage area

4. Procedure: The organization has identified picking as a process of warehouse management which involves material kit flow from warehouse to assembly.

4.1. As per order scenario as under. 22 – Shortage, 24 – Partial issue reported, 33 – Wall Stock/Backflush, 44 – Ready to pick, 99 – Report issue completed.

4.2. Respective team members released order (MO/RO/CO/DO) in M3, 44 status parts auto generated output document of picklist as below print at warehouse:

Document Owner:
Yuvraj Deshmukh

Approved By:
Nisha Solanki

Approved Date:
27-05-2026

Version:
4.0

Page:
2(7)

Picking Process.


Order number 1000632109	22/08/24 10:34 am	Address number 2580	1 (1)
Product 8999752700	To Location	Stock zone LP	
		Delivery number 1011654688	

6A011B003	Name WIRING	6A011B003	Name WIRING
Item 3222 3114 15	Quantity 1.00	Item 3222 3114 15	Quantity 1.00
Order 1000632109-8536	Delivery no 1011654688	Order 1000632109-8538	Delivery no 1011654688
Product 8999752700		Product 8999752700	
Lot/S.N		Lot/S.N	
Pl.grp CB3F	Tekn.ref Op 2580	Pl.grp CB3F	Tekn.ref Op 2580
5001	Draw.pos.	5001	Draw.pos.
Structure no 6060141450		Structure no 6060141450	


4.3. After picklist received the warehouse team create picking list in excel as per order. As well as create identification labels and print the same.

4.4. Pickers start picking as per list. When picker pick parts and report picklist through scanner / PC system. Posting procedure as below:

4.4.1. Login factory track as respective facility and select 5 – Manufacturing tab.



4.4.2. Select 2 for Pick MO as per pick list.



4.4.3. Add/Scan delivery number and press Next.

Document Owner:
Yuvraj Deshmukh

Approved By:
Nisha Solanki

Approved Date:
27-05-2026

Version:
4.0

Page:
3(7)

Picking Process.

PICK MO
SEARCH PICK LISTS

Customer

☒ Warehouse **CBC - 152 SED PC Nashik Main Whs**

☒ Delivery **1006714688**

☐ Customer

☐ Zone

☐ Equipment

4.4.4. Now we scan /add part number as per pick list and press next for entire list.

PICK MO
PICK LIST LINES
PICK: 1006714688*1 (MO)

Pick list line - Select

Loc	Item	Item Name	Qty	U/M	Lot	Cont	Del	Ord	Cons
68A008D02	0803415067	HEXAGON NIPPLE	1	EA			1008714688	1000347990	CB2F2002
68A009C02	0803415074	NIPPLE HEX	1	EA			1008714688	1000347990	CB2F2002
6ZD012A01	5727014870	BRACKET	1	EA			1008714688	1000347990	CB2F2002

4.4.5. Once we select all part against pick list we have multiple status :99” means we pick material.

4.4.6. For check entire output of MO issue we have “Click and Decide “report for PMS100 Material status.

AutoSave ☐ Off PMS100 Material status (12).xlsx Search (Alt+Q) Yuvra

Home Insert Page Layout Formulas Data Review View Help

Clipboard Font Alignment Number Styles Cells

facility	Product No.	MO	Sequenc	Operati	Item nu	Descrip	Quantit	U/M	Cost pri	Reporte	Issue m	Order t	Supplier	respons	Buyer	Status	Wareh
CB3	8997889000	100030684	8	2570	51123314	TUBE	1	PCS	352.8512	0	0	DP1	111441	MHNNIP	MHNNIP	22	CBE
CB3	8997889000	100032596	566	7000	55410852	PIN SET	2	PCS	47.3622	0	1	DP1	100149	MHNPOW	MHNPOW	24	CBE
CB3	8997889000	100027993	7	2580	51123134	CONTACT	1	PCS	96.9835	0	2	DP1	111368	MHNPOW	MHNPOW	33	CBE
CB3	8997889000	100032596	1014	6000	55719425	TUBE	1	PCS	9279.714	0	1	OP1	100202	MHNPOW	MHNPOW	44	CBE
CB3	8997889000	100027801	9018	2590	91103500	ATTACHM	1	EA	1157.488	1	1	Q11	111386	MHNEXTIN	MHNEXTIN	99	CBE

4.5. Issue picking material as per order to respective function / area as per lay dates plan.

4.6. Picking of Backflush Items as per production list and stock transfer through factory track.

4.6.1. Back flush item location in production area as per Manufacturing requirement. Parts replenishment step:

4.6.1.1. Warehouse persons check regular basis backflush location in production area.

4.6.1.2. Prepare list of Items as per demand of production.

4.6.1.3. Physical picking from warehouse location.

4.6.1.4. Post transaction in factory track as per required quantity

4.6.1.5. Bin material on Production backflush location.

4.6.1.6.

4.7. Process for system transaction in factory track

4.7.1. Login factory track as respective facility and select 3 – Inhouse.

Document Owner:
Yuvraj Deshmukh

Approved By:
Nisha Solanki

Approved Date:
27-05-2026


Version:
4.0

Page:
4(7)

Picking Process.



4.7.2. Select 1 Move balanced ID and add required DATA.



Factory Track PRD

MOVE BALANCE ID

SEARCH BALANCE ID

Search

☐	Search	
☐	From Location	
☐	Item	
☐	Lot	
☐	Container	

Document Owner:
Yuvraj Deshmukh

Approved By:
Nisha Solanki

Approved Date:
27-05-2026

Version:
4.0

Page:
5(7)

Picking Process.

4.7.3. Add required details and transfer stock from Main location to work center.

Factory Track PRD

MOVE BALANCE ID

LIST BALANCE ID

Balance ID - Select

Item	Item Name	Loc	Qty	U/M	Lot	Cont	Sts	Prio	Allocd	Movbl
0144320603	HEXAGON SCREW	6ZU303...	808	EA			APP	20213012	11 EA	808 EA
0144320603	HEXAGON SCREW	CB3F5001	-18	EA			APP	20232007	0 EA	-18 EA

Factory Track PRD

REPORT MOVE

Quantity (EA)

808.00

808.00

HEXAGON SCREW

From Location	☒	6ZU3037D01
Item	☒	0144320603
On Hand (EA)	☒	808.00
Quantity (EA)	☐	808.00
To Location	☒	CB3F5001

4.7.4. And then enter to transfer stock from warehouse location to work center.

4.8. Scenario 1: If we have inventory Gap in physical Vs System then we will go for reconciliation. After the approval of respective divisions, Head on Hard copy we post stock discrepancy in factory track.

DATE

Division

FORMAT : MANUAL-INV / 01

INVENTORY ADJUSTMENT APPROVAL

Sr. No	Part No	Description	Std Cost (INR)	System Qty	Physical. Qty	Adjustment Qty	Adjustment Value	Buyer	Part Class	Remark
1						0	₹ 0			
2						0	₹ 0			
3						0	₹ 0			
4						0	₹ 0			
5						0	₹ 0			
						Total cost	₹ 0			

Prepared By

Reviewed By

Approved By

Approved By

Approved By

System Adjusted By

Warehouse Coordinator

Deputy Manager - Internal SC

SCM Manager

Sourcing Head

Business Controller

4.9. For negative adjustment, the order type is R05.

Document Owner:
Yuvraj DeshmukhApproved By:
Nisha SolankiApproved Date:
27-05-2026Version:
4.0Page:
6(7)

Picking Process.

RO NEGATIVE ORDER DETAILS	
Order Type - Select	
Type	Name
R05	Inventory Adjustment, Negative

4.10. For positive adjustment the order type is R0.

RO POSITIVE ORDER DETAILS	
Order Type - Select	
Type	Name
R01	Inventory Adjustment, Positive

4.10. For positive adjustment order type is R0.

RO POSITIVE ORDER DETAILS	
Order Type - Select	
Type	Name
R01	Inventory Adjustment, Positive

5. Sub Activity:

5.1. Trolley Arrangement:

5.1.1. Update the kitting trolley board- (machine type, machine serial No/Mo number, station no/operation no, start date) before start of kitting/arrangement of bins on trolley.

5.1.2. Sticker on bins- it should have all details as per picking list (Part no, Description, part qty, etc.)

5.1.3. Small fabrication and delicate parts kept on trolley at lower side, to reduce pallet Qty, and proper utilization space of kitting trolley.

5.2. Picking of material from Lean to shade:

5.2.1. Insert foam or corrugated sheet on the pallet before pull the material to avoid damages.

5.2.2. Tag on pallet/ heavy big size parts (machine type, serial no, station no, pallet no, trolley no, etc.) before the start of material pull the material.

5.2.3. Kept material on pallet as per picking list assembly sequence (mention pallet no on kitting list to track material).

Document Owner:
Yuvraj DeshmukhApproved By:
Nisha SolankiApproved Date:
27-05-2026Version:
4.0Page:
7(7)

Picking Process.

5.2.4. Material should be arranged properly on pallet- material should not be overlap on each other, all material should be clear visible in pallet & easy to handle.

5.2.5. Material should be in unpacked, clean, painted, rust free condition.

5.2.6. All pulled Material handover to line feeder with shortage details and list for kitting.

6. Kit Extra & Line Return:

6.1. Kit extra material to be issued based on request slip from assembly with ref (Machine no, sub assembly no. etc.) transfer material SCM to Assembly warehouse after physically issued by SCM coordinator.

6.2. Physically returned material after completion of assembly it is to be returned with line return, after verification of material transfer material Assembly warehouse to SCM warehouse by coordinator.

6.3. Audit & Check Points:

6.3.1. Before issue kit, kit list & shortage list should be attached on kitting trolley.

6.3.2. All parts should have identification.

6.3.3. Take a kit audit photos of every trolley with both angle & pallet with android scanner & save on common drive to ensure all assembly material should be available, excluding shortages.

6.3.4. Issue kitting trolley as per assembly lay date.

6.3.5. Heavy or big size material provide online as per requirement or space available on station and it should be wash before issue.

6.3.6. Before issue kitting trolley & pallet should be clean by air pressure.

6.3.7. Pallet and kitting trolleys should be kept at a marked area at station.

6.3.8. Take operator signature on kit list after issue kit.

6.3.9. Engine kit, air kit, hose kit loos parts to be checked & declare shortages before start date.

6.3.10.

All kit parts should be painted or rust free.

6.3.11. Empty pallet should be removed from line immediately & issue available station material online as per requirement.

7. Records:

7.1. Picklist – M3 system generated

7.2. Excel List – Excel Picking list

7.3. Audit List