Assignment 2

Anmol Gairola
VIT Chennai Campus
19BCE1615

Type

Settings

[Read values] [Clear values]

🔍 Find in column Field

	Field	Measure		Role		Value mode		Values	
☐	# o_ring_ct	Continuous	⌄	None	⌄	Instantiated	⌄	6, 6	⚙
☐	# o_ring_failures	Continuous	⌄	Target	⌄	Instantiated	⌄	0, 2	⚙
☐	# temperature	Continuous	⌄	Input	⌄	Instantiated	⌄	53, 81	⚙
☐	# pressure	Continuous	⌄	Input	⌄	Instantiated	⌄	50, 200	⚙
☐	# launch_id	Continuous	⌄	None	⌄	Instantiated	⌄	1, 23	⚙

Default mode ⓘ

◉ Read metadata ◯ Pass (do not scan)

View Model: o_ring_failures

Regression

EVALUATION

Model Summary

ANOVA

Coefficients

MODEL VIEWER

Build Settings

Training Summary

Model Summary ⓘ

	1
R	0.822 [1]
R Square	0.676
Adjusted R Square	0.633
Std. Error of the Estimate	0.368