```
#include<Servo.h>
Servo s;
void setup()
 pinMode(2, OUTPUT);
 pinMode(3, INPUT);
 Serial.begin(9600);
 s.attach(5);
}
void loop()
 digitalWrite(2, LOW);
 digitalWrite(2, HIGH);
 delayMicroseconds(10);
 digitalWrite(2,LOW);
 float dur=pulseIn(3,HIGH);
 float dis=(dur*0.0343)/2;
 if(dis<330)
 s.write(180);
 delay(9000);
 }
 else
  s.write(0);
}
```

