

DRILL/ EXERCISE RECORD

Rig	Axom Rhino
Date & Location	22/09/2025 - DIU
Time	15:30
Type of Drilling, Training	Fire Drill followed by Search & Rescue / Mock Injury
Head Count	62

Chronological order of events during the drill:

Time	Event
14:40:10	Employee started responding to the alarm and start gathering at muster point
15:40:00	Alarm was raised for the fire drill by raising electrical siren
15:43:00	All employees were gathering at assembly point and roll call was started
15:43:20	Fire team was instructed to start firefighting by using CO2 fire extinguisher at camp DG set area
15:44:30	Fire fighting started by fire team
15:45:00	Roll call completed found 01 of the floorman was missing, last location identified near working area of camp DG set
15:45:45	Fire was extinguished by fire team and all equipment's check were performed by fire team
15:46:00	Information given to the incident commander on extinguishing of fire-by-fire team leader
15:47:00	Search & rescue team was instructed to start search and rescue operation by Incident commander
15:47:40	Person was found, initial check was performed by rescue team, call for medic and stretcher was given
15:48:30	Rig medic arrived on location & performed his check
15:49:00	Rig medic instructed to move the victim in ambulance for further sending him to nearby hospital
15:51:00	Person was transferred in ambulance by stretcher team
15:51:30	Ambulance left the site
15:55:00	Training was conducted for the employees on importance of mock drill & basic do's & don't at site, with closing meeting

Observation during the Drill / Exercise:

- Employees were not standing in a proper line (Five in a row) during mock drill and security personnel did not check the attendance or participate on mock drill
- The main door was not opened by the security team during the drill
- While lifting the stretcher, employees positioned the person's face towards the backside instead of facing forward

Areas of Improvement & Lessons Learnt:

- Awareness needs to be provided to employees on procedure which need to be followed during mock drill for roll call
- Security team to be instructed to take part in mock drill and keep the main door open in case of mock drill & actual emergency scenario
- Awareness needs to be given to stretcher team on right procedure of lifting & moving of victim in case of emergency

Corrective Action Taken:

- Awareness given to employees on procedure which need to be followed during mock drill for roll call in day & night TBT meeting
- Security team was instructed to take part in mock drill and keep the main door open in case of mock drill & actual emergency scenario
- Awareness given to the stretcher team on right procedure of lifting & moving of victim in case of emergency



SEROS OILFIELDS SERVICES INDIA
LIMITED
(f.k.a Starbit Oilfields Services India Limited)
CIN : UT1200MH2016PLC280188

Seros Oilfield Services India Limited

EMERGENCY RESPONSE DRILL REPORT

Rig : Axom Rhino

Report No: AXMRHINO/1/2025

SIS Report Date: 01/10/2026 11:55

Initiated by:	Name : Paramjit Singh Mistri	Initial Response Time: 3.00 min.	Number of participants: 62
Control Room Y (Offshore) :	Fire Team #1: 5	Streacher Team : 5	Maint. Team : 0
S & R Team : 5	Fire Team #2 :	Drill Muster: 13.00 min.	Abandon Muster (Offshore):
Total time of Drill :	25.00 min.		

Approved By:

PIC / OIM	Paramjit Singh Mistri		
	Name:	Signature	Stamp

Company Man	Mr. Saurabh		
	Name:	Signature	Stamp

Drill Photos

