

Dam Safety Inspection Summary

Scope

The authority inspects every high hazard dam each spring before the snowmelt flood season, and the field crew photographs each spillway gate in the open and closed positions.

Spillway findings

The Cedar Hollow spillway gate seized at forty percent open during the test lift and was rated urgent; the crew could not free it by hand.

Inspection results

Dam	Hazard class	Gate test	Rating
Cedar Hollow	High	Seized	Urgent
Birch Lake	High	Passed	Satisfactory
Mill Pond	Significant	Passed	Satisfactory
Quarry Reach	High	Slow	Watch

Follow-up actions

Quarry Reach gets a second lift test in June; Cedar Hollow stays drawn down until the gate is replaced.