Annual condition survey M/Y Aurelia

Vessel

M/Y Aurelia, 52 m motor yacht, built 2017, flag Cayman Islands, class LR.

Hull

Hull plating and coating in good condition; minor blistering on starboard quarter to be monitored.

Machinery

Main engines 2 x 1,940 kW, 11,820 running hours; oil analysis within limits.

Safety

Liferafts due for service in September 2026; EPIRB battery expiry 10/2026.

Recommendations

Renew shaft seals at next haul-out; service liferafts before 30/09/2026.

Machinery details

Item	Condition	Action
Port main engine	Good	Routine service at 12,000 h
Starboard main engine	Good	Routine service at 12,000 h
Generator 1	Fair	Replace exhaust elbow
Generator 2	Good	None
Bilge pumps	Fair	Main pump close to end of life
Steering gear	Good	None

Electrical

24 V and 230 V systems in good order; shore power connection to be inspected.

Conclusion

The vessel is in good condition and suitable for its intended use, subject to the recommendations above. Surveyor: J.-M. Castel, Méditerranée Marine Surveyors.

Scope and method

The survey was carried out afloat at Quai Antoine Ier, Monaco, on 14 and 15 May 2026, then on the hard during a short lift on 16 May 2026, in the presence of the Master and the Chief Engineer. Ultrasonic thickness measurements were taken on the bottom and side shell; machinery was observed running under load.

The survey is a condition survey for the manager and the owner; it is not a class or flag survey and does not replace the statutory certificates.

Hull – thickness measurements

Zone	Condition	Min. thickness	Action
Keel plate	Fair	18.5 mm	No action
Bottom fwd P	Fair	18.7 mm	Monitor
Bottom fwd S	Good	14.7 mm	No action
Bottom aft P	Fair	15.2 mm	No action
Bottom aft S	Good	18.8 mm	Touch-up coating
Side shell P	Good	17.8 mm	Monitor
Side shell S	Good	17.2 mm	No action
Transom	Good	18.2 mm	Touch-up coating
Bow thruster tunnel	Fair	18.2 mm	No action
Sea chest 1	Good	15.1 mm	No action
Sea chest 2	Good	18.1 mm	No action
Rudder P	Good	18.3 mm	Touch-up coating
Rudder S	Good	15.4 mm	Touch-up coating
Skeg	Good	15.1 mm	No action

Deck and superstructure

Teak deck in fair condition; caulking worn on the aft deck and the flybridge (approximately 18 m of seams). Stainless fittings in good order. Two windows on the main deck show minor delamination of the sealant.

Anchor windlasses and chain lockers in good order; chain marked every 25 m.

Safety equipment

Item	Status	Recommendation
Liferaft 12p A-pack (x2)	Service due 09/2026	Service before 30/09/2026
EPIRB 406 MHz	Battery expiry 10/2026	Replace battery and HRU
SART (x2)	Valid to 2028	None
Lifejackets SOLAS (x24)	4 lights inoperative	Replace lights
Lifebuoys (x4)	Good	None
Fire extinguishers (x18)	6 due for service	Service or replace
Fixed CO2 system engine room	Last test 03/2025	Test due 03/2027
Fire detection panel	Good	None
Pyrotechnics	Expire 11/2026	Replace
Emergency lighting	Good	None
Medical chest category A	Inventory partly expired	Restock

Photographs

No.	Subject
1	Starboard quarter blistering
2	Port shaft seal
3	Generator 1 exhaust elbow
4	Main bilge pump
5	Aft deck caulking
6	Liferaft certificates
7	EPIRB label
8	Engine room overview

No.	Subject
9	Steering gear
10	Shore power inlet
11	Tender cradle
12	Windlass

Recommendations and priorities

No.	Recommendation	Priority	Before
1	Service both liferafts	High	30/09/2026
2	Replace EPIRB battery and HRU	High	31/10/2026
3	Replace main bilge pump (end of life)	High	Next yard
4	Renew shaft seals	Medium	Next haul-out
5	Replace generator 1 exhaust elbow	Medium	31/12/2026
6	Re-caulk aft deck seams	Low	Next yard
7	Replace pyrotechnics	Medium	30/11/2026
8	Restock medical chest	Medium	30/06/2026

Inspection – Main deck

Visual inspection and function test in the presence of the Chief Engineer.

Item	Condition	Remarks
Teak deck	Fair	Cosmetic marks
Hatches	Good	Minor wear
Windows	Good	No defect noted
Doors	Fair	Serviced 2025
Handrails	Satisfactory	Monitor
Lighting	Good	Minor wear
Drainage	Satisfactory	No defect noted

Inspection – Upper deck and flybridge

Visual inspection and function test in the presence of the Chief Engineer.

Item	Condition	Remarks
Hardtop	Satisfactory	No defect noted
Helm station	Fair	No defect noted
Radar arch	Good	Minor wear
Sunbeds	Good	Monitor
Bar unit	Good	Minor wear
Crane	Fair	Cosmetic marks

Inspection – Guest accommodation

Visual inspection and function test in the presence of the Chief Engineer.

Item	Condition	Remarks
Master cabin	Good	No defect noted
VIP cabin	Satisfactory	Cosmetic marks
Twin cabin 1	Satisfactory	Serviced 2025
Twin cabin 2	Good	Minor wear
Bathrooms	Good	No defect noted
HVAC	Good	Minor wear

Inspection – Crew area and galley

Visual inspection and function test in the presence of the Chief Engineer.

Item	Condition	Remarks
Crew mess	Satisfactory	Serviced 2025
Crew cabins	Satisfactory	No defect noted
Galley equipment	Satisfactory	No defect noted
Laundry	Good	No defect noted
Cold rooms	Good	No defect noted

Inspection – Engine room

Visual inspection and function test in the presence of the Chief Engineer.

Item	Condition	Remarks
Main engine P	Fair	No defect noted
Main engine S	Good	Monitor
Gearboxes	Good	No defect noted
Generator 1	Satisfactory	No defect noted
Generator 2	Fair	Serviced 2025
Fuel separators	Satisfactory	No defect noted
Bilge system	Fair	Monitor
Fire pumps	Good	Serviced 2025
Ventilation	Satisfactory	Monitor
Watermakers	Satisfactory	Minor wear

Inspection – Steering and propulsion

Visual inspection and function test in the presence of the Chief Engineer.

Item	Condition	Remarks
Steering gear	Good	Monitor
Rudder stocks	Good	Serviced 2025
Shaft lines	Good	Serviced 2025
Propellers	Good	No defect noted
Stabilisers	Good	Serviced 2025
Bow thruster	Good	No defect noted