Light sersor-IC@ OXID PH 7.0 Voltage = 1.52 set gain to 1/8 PH = 5.32 integration time to 25 ms for long run, see slife 257! also, twist wires! PH 4.0 Vollage = 2.04 PH = 7.14 Moisture To 2.94(slope)+ offset=4,0 1.52 (slope) + offset = 7.0 1100 plue 3900 offset=4,0-2,04(slope) 1.52(slope)+4,0-2,04(slope)=7.0 4.0-0,52(slope)=7 %= -100 X + 6 100 = -106 (1100) +6 0.52 (Stope) = 3 9.52 lope = -5,7692 6=157.899 offeet=4.0-2.04(-5.7692) 62(-100) X 2/55 5 offset = 15.7692 -1.7592