ELECTRICAL SAFETY

for Staff and Students in ECEE Power Laboratory

NEVER WORK ALONE

If you are working with energized circuits or equipment over 50 volts peak, make sure that at least one other person can see you and hear you.

VOLTAGE RULES

If you intend to work on a project using power sources **over 50 volts peak**, you must receive **specific training** from your Instructor or TA **before** any work on the project begins.

PREVENT ACCIDENTS: FOLLOW THIS ADVICE

- Never hurry. Work deliberately and carefully.
- Connect to the power source LAST.
- If you are working with a lab kit that has internal power supplies, turn the main power switch OFF before you begin work on the circuits. Wait a few seconds for power supply capacitors to discharge. These steps will also help prevent damage to circuits.
- If you are working with a circuit that will be connected to an external power supply, turn the
 power switch of the external supply OFF before you begin work on the circuit.
- Check circuit power supply voltages for proper value and for type (DC, AC, frequency) before energizing the circuit.
- Do not run wires over moving or rotating equipment, or on the floor, or string them across walkways from bench-to-bench.
- Remove conductive watch bands or chains, finger rings, wrist watches, etc., and do not use metallic pencils, metal or metal edge rulers, etc. when working with exposed circuits.
- When breaking an inductive circuit open the switch with your left hand and turn your face away to avoid danger from any arc which may occur across the switch terminals.
- When using large electrolytic capacitors be sure to wait long enough (approximately five time constants) for the capacitors to discharge before working on the circuit.
- All conducting surfaces intended to be at ground potential should be connected together.

QUESTIONS ABOUT SAFETY

Any questions about safety should be brought to the attention of your TA or instructor.
 If problems arise that cannot be solved at this level, you should contact the ECEE Safety Officer:

Wayne Gardner, Rm: ECEE 1B22, Tel: (303) 492-8917, Email: wayne.gardner@colorado.edu

ADDITIONAL CAUTIONS

- The Power Laboratory is equipped with Ground Fault Current Interrupt (GFCI) circuit breakers. Check for leakage paths to ground when breakers trip repeatedly and the problem is not due to an overload.
- Any equipment used in the laboratory must be equipped with a standard three-prong AC plug or a two-pronged polarized plug.
- All exposed non-current-carrying metal parts of fixed and portable equipment that may accidentally become energized should be grounded.
- All electrical equipment or apparatus that may require frequent maintenance must be capable of being completely disconnected from the power source.
- Do not bring into the lab or use in the lab equipment that does not conform to these rules without specific permission from your instructor or TA.

BASIC ELECTRICAL SAFETY PRACTICES

The following safe work practices can prevent electrical shock.

A. Safe Work Practices

- 1. Turn off and unplug equipment (instead of relying on interlocks that can fail) before removing the protective cover to clear a jam, replace a part, adjust or troubleshoot. Ask a qualified person to do the work if it involves opening equipment and creating an exposure to energized parts operating at 50 volts or more.
- 2. Don't use an electrical outlet or switch if the protective cover is ajar, cracked or missing.
- 3. Only use DRY hands and tools and stand on a DRY surface when using electrical equipment, plugging in an electric cord, etc.
- 4. Never put conductive metal objects into energized equipment.
- 5. Always pick up and carry portable equipment by the handle and/or base. Carrying equipment by the cord damages the cord's insulation.
- 6. Unplug cords from electrical outlets by pulling on the plug instead of pulling on the cord.
- 7. Use extension cords temporarily. The cord should be appropriately rated for the job.
- 8. Use extension cords with 3 prong plugs to ensure that equipment is grounded.
- 9. Never remove the grounding post from a 3 prong plug so you can plug it into a 2 prong, wall outlet or extension cord.
- 10. Re-route electrical cords or extension cords so they aren't run across the floor, under rugs or through doorways, etc. Stepping on, pinching or rolling over a cord will break down the insulation and will create shock and fire hazards.
- 11. Don't overload extension cords, multi-outlet strips and wall outlets.
- 12. Heed the warning signs, barricades and/or guards that are posted when equipment or wiring is being repaired or installed or if electrical components are exposed.
- B. Check for Unsafe Conditions (either before or while you're using equipment:)
- 1. Is the cord's insulation frayed, cracked or damaged, exposing the internal wiring?
- 2. Are the plug's prongs bent, broken or missing, especially the third prong?
- 3. Is the plug or outlet blackened by arcing?
- 4. Was liquid spilled on or around the equipment?
- 5. Are any protective parts (or covers) broken, cracked or missing?

- 6. Do you feel a slight shock when you use the equipment?
- 7.
- Does the equipment or the cord overheat when it is running?

 Does the equipment spark when it is plugged in or when switches or controls are used? 8.

\sim	If ,	VALL A	hearva	any of	thoso	uncafo	conditio	nc:
C.	ш,	you o	naci ve	ally Oi	เมษอย	ulisale	Conditio	115.

- 1. Don't use (or stop using) the equipment.
- Tag/label the equipment UNSAFE--DO NOT USE and describe the problem. 2.
- 3. Notify your TA or instructor.

Electrical	safety	is for	everyone	because	even	contact	with	the	standard	117	volt	electrical	circuits,
which we	consta	ntly us	se, can be	lethal und	der ce	rtain con	dition	ns.					

which we constantly use, can be lethal under certain conditions.
Tear HereTear Here
I CERTIFY THAT I HAVE READ AND UNDERSTOOD "ELECTRICAL SAFETY FOR
STAFF AND STUDENTS IN ECEE POWER LABORATORY" INCLUDING "BASIC
ELECTRICAL SAFETY PRACTICES" AND I AGREE TO ABIDE BY THESE RULES AT
ALL TIMES WHILE I AM ENROLLED IN ANY POWER LABORATORY COURSE, OR WHILE TEACHING OR ASSISTING IN A LABORATORY COURSE.
FILL OUT, SIGN, AND RETURN THE BOTTOM HALF OF THIS PAGE TO YOUR TA,
SIGNED:
PRINT NAME:
DATE: