

Churn (fpm)	1M	VectorReg LPM	VectorReg LPM	VectorReg LPM	VectorReg LPM	VectorReg LPM	VectorReg LPM	VectorReg LPM
		Vector FCFS_CT	Vector FCFS_CT	Vector FCFS_CT	Vector FCFS_CT	Vector FCFS_CT	Vector FCFS_CT	Vector FCFS_CT
	100K	VectorReg LPM	VectorReg LPM	VectorReg LPM	VectorReg LPM	VectorReg LPM	VectorReg LPM	VectorReg LPM
		Vector FCFS_CT	Vector FCFS_CT	Vector FCFS_CT	Vector FCFS_CT	Vector FCFS_CT	Vector FCFS_CT	Vector FCFS_CT
	10K	VectorReg LPM	VectorReg LPM	VectorReg LPM	VectorReg LPM	VectorReg LPM	VectorReg LPM	VectorReg LPM
		Vector FCFS_CT	Vector FCFS_CT	Vector FCFS_CT	Vector FCFS_CT	Vector FCFS_CT	Vector FCFS_CT	Vector FCFS_CT
	1K	MapTable Vector	MapTable Vector	MapTable Vector	MapTable Vector	MapTable Vector	MapTable Vector	MapTable Vector
		VectorReg LPM	VectorReg LPM	VectorReg LPM	VectorReg LPM	VectorReg LPM	VectorReg LPM	VectorReg LPM
	0	DchainTable	DchainTable	DchainTable	DchainTable	DchainTable	DchainTable	DchainTable
		MapTable Vector	MapTable Vector	MapTable Vector	MapTable Vector	MapTable Vector	MapTable Vector	MapTable Vector
		VectorReg LPM	VectorReg LPM	VectorReg LPM	VectorReg LPM	VectorReg LPM	VectorReg LPM	VectorReg LPM
		DchainTable	DchainTable	DchainTable	DchainTable	DchainTable	DchainTable	DchainTable
		0.0	0.2	0.4	0.6	0.8	1.0	1.2
		Skew (Zipf parameter)						