

Inspection Record — Recovery Fleet, Third Quarter

Reference INS-REC-2301 Revision A Unit: 12 Field Workshop

FICTIONAL CONTENT — generated for platform testing only.

1 Inspection Window

Inspections were carried out between 12 and 23 August. A total of 14 recovery vehicles were presented, of which 14 were inspected and none were withdrawn before inspection.

2 Outcome Summary

Of the 14 vehicles inspected, 9 passed with no defects, 3 passed with deferred minor defects, and 2 failed and were immobilised. The two failures were both attributed to brake system faults under SOP-BRK-031.

3 Deferred Defects

The 3 deferred defects comprised: one cracked mirror arm, one unserviceable cab heater, and one worn tow-pin retaining clip. All three are scheduled for rectification at the next scheduled service.

4 Rope Findings

Two vehicles were found with winch rope approaching the discard criterion of TM-GEN-220. Both ropes were replaced during the inspection window and the old ropes destroyed.

5 Next Inspection

The next quarterly inspection is scheduled for the window 11 to 22 November. Vehicles carrying deferred defects will be presented first.