
12-electrode three-phase rotating-field geometry
Phase A
Phase B
Phase C
central aperture
3
4
2
5
1
6
0
7
11
8
10
9
Phase order around orbit:
ABCABCABCABC
U_A = U₀ sin(Ωt)
U_B = U₀ sin(Ωt − 120°)
U_C = U₀ sin(Ωt + 120°)
10
5
0
−5
−10
y (mm)
−10
−5
0
5
10
x (mm)