Project 9 - DDE Messaging

Saturday, 8 August 2020 10:54 PM

A machine is to cycle between two modes.

Each mode has two functions (lets say functions F1 and F2).

The process is continuous as start-up, and each function lasts for 10 seconds.

Details of which mode & function the process is in need to be sent to Excel.