
Project 6 Hourmeter

Sunday, 2 August 2020

4·11 PM

In this project we're making a system that will track the runtime of a host plant. The time will only be taken when the plant is running, and we will use a bit to represent this. This system will include a reset button.



This is basically the same as that clock you made for object-oriented (only without the objects).

You want the following:

Bits:

- System Running
- Reset Button

Integers:

- Seconds (0 60)
- Minutes (0 60)
- 100's if hours (count from 0 9)
- 1000's of hours (count from 0 999)